

Service Price list

The repair flat rates refer to the elimination of electronic faults including 300 individual measurements, hearing test, test run and device cleaning. All rechargeable batteries and batteries are replaced as part of a repair. New packaging is included if necessary. Repairs of devices that are not listed in the price list are processed with a cost estimate. We charge a processing fee of €300.00 excluding VAT for this estimation. Shipping costs for collections will be invoiced separately. Possible expenses incurred by the retailer are not included, as well as custom fees and taxes.

If the product is registered at <https://burmester.services/warranty/> after the repair as part of the flat-rate repair fee, we offer 1 year warranty on the entire device (except for hard disks, unless they were replaced during the repair).

SERVICE-PRODUCTS	RETAIL PRICE
111 Musiccenter	2.650,00 €
069 CD-Player	2.500,00 €
077 Preamplifier	2.350,00 €
808 MK5 Preamplifier	4.450,00 €
909 MK5 Power Amplifier	3.900,00 €
151MK1/MK2 Musiccenter	1.500,00 €
089 CD-Player	1.650,00 €
088 Preamplifier	1.350,00 €
100 Phono Preamplifier	1.650,00 €
102 CD-Player	1.250,00 €
061 CD-Player	1.250,00 €
035 Preamplifier	1.200,00 €
101 Integrated Amplifier	1.700,00 €
082 Integrated Amplifier	1.400,00 €
032 Integrated Amplifier	1.500,00 €
036 Power Amplifier	1.150,00 €
956 MK2 Power Amplifier	1.400,00 €
948 Power Conditioner	1.550,00 €
911 MK3 Power Amplifier	1.600,00 €
150 Musiccenter	950,00 €
099 Preamplifier	1.100,00 €
216 Power Amplifier	2.000,00 €
218 Power Amplifier	2.900,00 €
161 All in One	2.250,00 €

The following models cannot be repaired as part of our service offer.

992 CD-Player, 917 CD-Player, 006 CD-Player

MODIFICATIONS

RETAIL PRICE

909 MK3	909 (Mk3) modes on Mk5 with silver wiring throughout, Modes of the protective circuit, loudspeaker relay replaced, Conversion of the rear panel incl. C19 power supply, including new C19 mains cable	6.900,00 €
911 MK1/ MK2	911 (MK1/MK2) modes on MK3 with continuous silver wiring, Completely new amplifier board with optimized circuit concept	6.750,00 €
956	Modification to 956 MK2 with extended CLASS A range, Silver cable in the input area and reinforced power supply unit	2.600,00 €
956 MK2	956 MK2 with optional silver speaker wiring	3.900,00 €
111 - Modi. 1	Modification to X-AMP3, incl. modification of base card, Power supply unit, USV-board renewed, software update	4.200,00 €
111 - Modi. 2	Modification to X-AMP3, conversion from HDD to 2 x 4Tb SSD, incl. modification base card, power supply unit, USV-board renewed, software update	6.000,00 €
111 - Modi. 3	Modification from HDD to 2 x 4Tb SSD (without X-AMP3), incl. modification base card, power supply unit USV-board renewed, software update	4.200,00 €
961 MK1 / MK2	Upgrade to 961MK3 including new midrange / tweeter & new crossover	5.500,00 €
995 MK1 / MK2	Conversion to 995MK3 including new midrange / tweeter & new crossover	4.900,00 €

Warranty extension as part of the modification or repair flat rate can be done online or in written form . We reserve the right a separate cost estimate must be prepared for damage caused by force majeure, overvoltage, lightning damage and external intervention.

Repairs to devices that are not listed in the price list are determined with a classic cost estimate of €357.00 including VAT.
Shipping costs for collections will be invoiced separately.